



## CHALLENGES THEY WERE FACING

- Maintenance costs and downtime - wear plant change out is 88 days per annum - overlay plates only lasting 4 weeks.
- Eliminate confined space work.
- Reduce maintenance on a Skirt Board conveyor section from chute discharge.

# LAMINITE® SKIRT LINERS VS OVERLAY PLATE

MINING MASSIVE SAVINGS

A MAJOR W.A. DIAMOND MINER  
ELIMINATED 53 OUT OF 88 CONFINED  
SPACE EVENTS PER CHUTE BY CHANGING  
TO LAMINITE® SKIRT BOARD LINERS



**SAFETY  
ALWAYS**



Overlay liner wear plates at installation

Overlay liners inspected 4 weeks later

Laminite® wear plates installed where overlay plates were

Same Laminite® wear plates 10 weeks later

## OUR SOLUTION

- Replace Overlay plate with Laminite® Skirt Board Liners.
- Laminite® Skirt Board Liners lasted 10 weeks.
- Plant down time for wear plate change out is now 35 days per annum.

